

FS 22

Floor Stripper

Piso Estripádo

- Biodegradable
- Environmentally Responsible Ingredients



Formula

#4556

Recyclable

packaging

This product meets Green Seal™ Standard GS-40 based on effective performance and protective limits on VOCs and protective limits on VOCs and human & environmental toxicity.



Technical Data & Training Sheet

PRODUCT DESCRIPTION:

A highly effective, fast acting, non-corrosive, low odor, floor finish and wax remover. This product will strip FOCUS ZF 33 Zinc-Free Floor Finish as well as other green floor finishes.

USES:

Easy and fast removal of multiple coats of floor finish, wax or acrylic seal with or without the use of a conventional floor machine and stripping pad.

ADVANTAGES:

GREEN SEAL™ CERTIFIED under GS-40 standard for industrial and institutional floor-care Environmentally responsible formula does not contain 2-butoxyethanol, ammonia, nonylphenol surfactants, dye or fragrance.

SPECIFICATIONS:

pH: 11

Color: Clear, colorless.

Solubility in Water: Complete Odor: Mild, No fragrance added

Flash Point: N/A

Viscosity: Water thin liquid Weight per Gallon: 8.5 Lbs.

PRODUCT/CONTAINER **DISPOSAL:**

Dispose of used/unwanted product according to state and local regulations. Offer container for recycling.

SIZES AVAILABLE:

1 Gallon, 5 Gallons, 30 & 55 Gallons.

PURPOSE	DILUTIONS
LIGHT BUILD-UP	1:8 (16 oz. concentrate per gallon of cold water) 1:8 (16 onzas concentrado cada galón de agua fría)
MODERATE BUILD-UP	1:4 (32 oz. concentrate per gallon of cold water) 1:4 (32 onzas concentrado cada galón de agua fría)
HEAVY BUILD-UP	1:2 (64 oz. concentrate per gallon of cold water) 1:2 (64 onzas concentrado cada galón de agua fría)

DIRECTIONS FOR PRODUCT USE:

NOTE: Improper dilution may result in damage to surfaces and may increase the risk of health effects.



Stripper should be diluted with cold water!



It is recommended that protective gloves and safety glasses be worn when using this and all cleaning

Refer to SDS for further safety information.



1. Apply a liberal amount of solution to the floor and let penetrate for 3 to 5 minutes.



2. Work in small enough areas so as not to allow stripper to dry. Use another wet mop to pick up the re-emulsified floor finish.



3. For heavy build-up a floor machine may be necessary.



4. Rinse floor with clean water and allow to dry thoroughly.



5. Apply 3-4 coats of ZF 33 Zinc-Free Seal & Finish with mop or applicator to produce a long lasting and durable shine.









